ž%Ž(Ł%!. ·

6mi g|b['h\]g'd fc Xi Whžmci 'U[fYY 'hc 'h\Y 'Zc ``ck]b['hY fa g

K UffUbhm7 cbX]h]cbg

5 bma cX]ZMUhjcbžhUa dYfjb[žcfi bUi h\cfjnYX`fYdUjfcZh\jgdfcXi Whk]"j cjX`h\Y`k UffUbhm".⊋mci `XYWjXY`hc'U`hYfz"Wi ghca]nYž"cfch\Yfk]gY`a Yggik]h\`]hžmci ÑY´Zi ``mi fYqdcbqjV`Y`Zcfh\Y`ci hWca Y"

@UV]]ImiK U]j Yf

K Y 'UfY 'bch'fYgdcbg]V Y 'Zcf'UbmXUa U[Yž]b↑fmžcfW.Ucg'WU gYX 'Vm]a dfcdYfigYžibUih\cf]nYX 'a cX]Z]WUh]cbgžcfZU]ifY 'bc 'Zc``ck 'h\Y 'dfcj]XYX ']bghfi Wh]cbg" '₹mci ÑY 'UVci h'bc 'Xc' 'gca Yh\]b['ei Ygh]cbUV 'Yžghcd 'UbX' WcbhUWhig Z]fgh' 'GYf]ci gm'

±bHYbXYX T gY

H. IgʻdfcXi Wh'IgʻXYgI[bYX Zcf**bcfa U`i gY`]bʻcj YfUbX]b[!** "I glb[']h'ZcfUbmh.]b['Y`gY`]gʻYbhJfY`mUhmci fck bʻflg_"K Y`WUbfhidfchYWhmci 'Zfca 'VUX']XYUgʻcffYW_YggʻYldYfla YbhUhJcb"

GUZYhmi:]fgh

IgY h\]gdfcXiWhfYgdcbg]V`mUbX`k]]h\h\Y`dfcdYf`hcc`gʻUbX`Yei]daYbh"\ZmcifffY` ibgifY`UVcihUbmh\]b[žXcbffi]adfcj]gY[fYUW\cihhc`igʻZ[fgft"8cbffiV`UaY`ig`]Zmci` \ifhmcifgY`ZXc]b[`gcaYh\]b[`kY`YId`]W]hmhc`X`mci`bchhc`Xc"

; chei Yg/]cbg3'8cbf/lik]b[']h''7 cbhUWhi g'VYZcfY 'Xc]b['Ubnth\]b['ci hg]XY'h\Y'gWcdY'cZ bcfa U`'i gY''

ł Bcfa U`l gY]b Cj Yf UbX]b[

H.]gfccZfUW_]gXYg[[bYX fc k]f\gtUbX f\Y fmd]MU "XYa UbXgcZcj YfUbX]b["UbX cZtfcUX UXj YbHi fYgt]bWi X]b[.

9. dog fY fc Ci fXccf7 cbX]fjcbg FYUgcbUVY YI dog fY fc k YUlh\Yfzg W. UgfU]bžk]bXžUbX g b][\hzi bXYfbcfa U" ci fXccfi gY"

K∖UhfogʻBch±bWiXYX]b Bcfa UʻlgY.


9 WYX]b['KY][\h7 UdUW]ma`CjYfcUX]b['h\YfUW_VYmcbX]hgghUhYX'a Ul]aia'kY][\h']a]hik\Yh\YfgUh]cbUfmicf]b'achicb''

ad dUW bycf7 c"]gjcbg 8UaU[Y'fYg' hjb[Zica 'UWWjXYbhg2]adUWngk]h\"ck!\Ub[]b['cVYWhg2cfch\YfWc"]gjcbg"
ad dfcdYf5HdUWcaYbh:U]ifY hc'gYW fY'mZUghYb WUf[czk\]M\`aUmfYg' hjb XUaU[Y'hc'h\Y'fUW_zjY\]MYzcf]hYag'
VY]b['hfUbcdcfhYX"


9. HYA Y'7 cbX]Hcbg 'G Va Yfglcb']o 'k UHYfžYl dcg fY 'bc 'Wcffcgjj Y'a UHYf]U'gz'cfdfc'cb[YX'i gY']o'Yl HYA Y'k YUH\Yf VYmcbX'h\Y'dfcXi WhajqdYWZ]WUh|cbd'

I bUI h.cfjnYX:A cX]ZWUjjcbg:8fj"]o[žW hijo[žcf'U'HYf]o['h\Y'fUW_]o 'Ubmk Umi\Uhi\ZY/Wig]igigfi Wi fU'']ohY[f]m'i

2Ł* óó\M/+) /1, , +. O[2Ł* óó\M/+) %/OŁ#. Ł) Y[2Ł* óóŒ+"". +Łž



. ++" . ŁŽ' . LEXUS GX470/TOYOTA LC120



%/0.1Ž0%*/

+19 A "BC"	D5 FHBI A 69F	8 9G7 F ĐH€ B	E HM
%	\$3\$2\$%\$%\$%	F<'F5#@	%
&	\$3\$2\$%\$%\$&	@ F5 €	%
'	\$3\$2\$% \$%\$'	8 9: @97 HC F	%
(\$\$\$\$!%\$3	%%0\$A A '7 FC GG65 F	,
)	, , \$\$\$!\$*\$&6	A * 'L '%) A A 'K 5 G< 9F '6C 'GG	*
*	, , \$\$\$!\$&\$%6	A * L "%L "&\$A A "HL "6C "CG	*
+	, , \$\$\$! \$* \$+G	A , 'L'&('A A 'K 5G<9F'%!,	%&
,	, , \$\$\$!\$&\$&G	A , L '%''&) 'L ') \$A A ' <l '<8="" 'gg<="" td=""><td>%&</td></l>	%&
-	\$\$\$\$!\$) \$+	&(AA GD579F	%&

FOLLOWING THE CORRECT ORDER OF OPERATIONS IS CRITICAL

TOOLS/SUPPLIES NEEDED

- >> T30 TORX DRIVER
- >> 13MM WRENCH
- >> WEATHER RESISTANT BLACK SILICONE (EG. DAP DYNAFLEX ULTRA)
- >> COPPER-BASED ANTI SEIZE (USE ON ALL BOLTS)
- >> M8 X 1.25 TAP (FOR CHASING OEM THREADS)

PREPARATION NOTES:

- >> REMOVE ALL OEM ROOF RACK COMPONENTS AND HARDWARE
- >> THOROUGHLY CLEAN ALL SURFACES
- >> INSPECT THE (12) M8 OEM THREADS. ENSURE THEY ARE CLEAN AND FREE OF DEBRIS OR DAMAGE. CHASE THREADS WITH TAP IF NECESSARY
- >> RUBBER TRIM IS PROVIDED, BUT CLEAR PPF MAY BE INSTALLED UNDERNEATH THE DEFLECTOR AS AN EXTRA MEASURE TO PROTECT PAINT



STEP 1:

APPLY A BEAD OF SILICONE AROUND EACH M8 HOLE IN THE ROOF AND OVER THE THREADS. PLACE SPACERS (9)

OVER THE HOLES

STEP 2:

INSTALL THE RAILS ① ,② USING M8 SCREWS $\ensuremath{\mathfrak{B}}$ AND WASHERS ⑦ , ONE SIDE AT A TIME. DO NOT YET TIGHTEN THE BOLTS

STEP 3:

INSTALL 8 CROSSBARS 4 USING 6 , 5 . LEAVE BOLTS LOOSE UNTIL ALL BARS ARE SET TO THE DESIRED SPACING, THEN TIGHTEN ALL CROSSBAR BOLTS

STEP 4:

ONCE RAILS ARE ALIGNED FRONT TO BACK, TIGHTEN ALL 12 M8 BOLTS.

STEP 5:

INSTALL THE DEFLECTOR ③ USING REMAINING BOLTS, NUTS ⑥ ,⑤ . SLIDE DEFLECTOR UNTIL IT TOUCHES ROOF LINE, ENSURE EVEN CONTACT THROUGHOUT, THEN TIGHTEN 4 BOLTS.

NOTE: TAKE EXTRA PRECAUTIONS WHEN REMOVING OEM BOLTS. LOOSEN BOTH BOLTS PER "SET" BEFORE COMPLETELY REMOVING, AS THE WELD KEEPING THEM IN PLACE CAN POSSIBLY BREAK. DO NOT USE AN IMPACT WRENCH WHEN REMOVING OR INSTALLING THE M8 BOLTS. IF THE OEM NUTS BREAK OFF THE RECOMMENDED FIX

IS TO INSTALL AN M8 RIV NUT IN IT'S PLACE. REMOVE HEADLINER TO EXTRACT BROKEN WELD NUT.

